



CTC211 Chassis Configuration

**SCAN RATE CONVERTER
MODULE**

PROBLEM: PICTURE HAS A THIN BLUE LINE ON LEFT SIDE OF SCREEN 1/4" IN DIAMETER ON MOST SCENES. REPLACING SCAN RATE CONVERTER(PART NUMBER 254349) FIXES PROBLEM. THE SCAN RATE CONVERTER IS SIMILAR TO THE FLEX CONVERTER IN HITACHI UNITS.